

AMENDMENTS TO THE SPECIFICATION:

Please amend the specification as follows:

On page 6, replace paragraph [019] with the following new paragraph [019]:

[019] As shown in Figure 1, the holder 10 ensures that the transducer assemblies 50 (and transducers 51) are held at the correct horizontal location, in this case axis ~~70~~ 12, which corresponds to the 4th intercostal space at the midaxillary line.